

HISTORIC AMERICAN ENGINEERING RECORD

HAER
COLO
35-ESKY
5-

INDEX TO PHOTOGRAPHS

HAER No. CO-85

Hondius Water Line

(Hondius-Beaver Water Delivery System)

(Hondius-Beaver Pipeline)

1.6 miles northwest of Park Headquarters

Building and 1 mile northwest of Beaver

Meadows Entrance Station

Rocky Mountain National Park

Estes Park Vicinity

Larimer County

Colorado

Documentation: 17 photographs
24 data pages

Lisa V. Lynch, Photographer, September 1997

- | | |
|---------|--|
| CO-85-1 | INTAKE CHANNEL LOOKING NORTHEAST; WATER FROM BEAVER BROOK ENTERS THE INTAKE CHANNEL HERE. |
| CO-85-2 | INTAKE CHANNEL LOOKING NORTHWEST; GATES 1, 2, AND 3 SHOWING. |
| CO-85-3 | INTAKE CHANNEL LOOKING WEST; DEBRIS FILTER SCREEN IN GATE 2. |
| CO-85-4 | GATES 1 AND 2, INTAKE CHANNEL LOOKING EAST. |
| CO-85-5 | GATE 5, INTAKE CHANNEL LOOKING SOUTH: WATER FROM GATE 5 ENTERED DITCH AND IRRIGATED HONDIUS' FIELDS. |
| CO-85-6 | GATES 3, 4, AND 5, INTAKE CHANNEL LOOKING EAST; WATER THAT PASSED INTO PIPES ENTERED SETTLING VAULT. |
| CO-85-7 | INTAKE CHANNEL AND SETTLING TANK, SOUTHWEST SIDE. |
| CO-85-8 | SETTLING TANK, WEST SIDE: WATER PIPE FROM INTAKE STRUCTURE IN FOREGROUND. |

- CO-85-9 SETTling TANK, NORTHWEST SIDE.
- CO-85-10 SETTling TANK CLEAN-OUT DOORS, SOUTH SIDE: USED TO
CLEAN DEBRIS FROM SURFACE OF WATER IN SETTling TANK.
- CO-85-11 SETTling TANK OVERFLOW CHANNEL, NORTH SIDE.
- CO-85-12 SETTling TANK EXTENSION, SOUTHEAST SIDE.
- CO-85-13 SETTling TANK, OVERFLOW DITCH, NORTHEAST SIDE;
OVERFLOW DITCH RETURNED EXCESS WATER TO BEAVER
BROOK.
- CO-85-14 IRRIGATION DITCH LEADING FROM GATE 5 TO HONDIUS'
FIELDS, LOOKING NORTHWEST.
- CO-85-15 STORAGE SHED, SOUTHEAST SIDE.
- CO-85-16 STORAGE SHED DOOR DETAIL, SOUTH FRONT.
- CO-85-17 SPRINGHOUSE, SOUTHWEST SIDE: NOTE BROKEN GRANITE
FOUNDATION FROM SURROUNDING HILLSIDES.